

# INFORMATION REPORT

25X1A

COUNTRY Philip Approved For Release 2003/10/01 : CIA-RDP80-00809A000500350162-1

SUBJECT Port Information, Santa Cruz (Balvarte),  
Zambales Province25X1A PLACE ACQUIRED  
(BY SOURCE)

DATE ACQUIRED (BY SOURCE)
DATE (OF INFO.)

DAIS NO.	
OCI NO.	

DATE DISTR. 5 Jan 54

NO. OF PAGES 1

NO. OF ENCLRS.

SUPP. TO  
REPORT NO.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES. WITHIN THE MEANING OF TITLE 18, SECTIONS 700 AND 704, OF THE U.S. CODE, AS AMENDED, ITS TRANSMISSION OR REVELATION OF ITS CONTENTS TO OR RECEIPT BY AN UNAUTHORIZED PERSON IS CRIMINALIZED BY LAW. THE REPRODUCTION OF THIS REPORT IS PROHIBITED.

25X1X

THIS IS UNEVALUATED INFORMATION

THIS IS UNEVALUATED INFORMATION
---------------------------------

The office of Naval Intelligence (12ND, No 138-53) furnished the following information to CIA for IAC Dissemination in accordance with par 3c of NSCID #7-7

1. Location. The town of Santa Cruz is situated on the Northeast shore of a small shallow bay. The loading dock, however, is on the south shore of the bay at Balvarte ( $15^{\circ} 45'.N$   $119^{\circ} 53.5'E$ ) and is approached by a channel through the reefs.
2. Entrance. Entrance from sea should only be made during the day and is made between Hermanna Mayor Island and Hermanna Island with the southern and highest point of a flat topped mountain bearing  $60^{\circ}$  true which should be steered for until the dock range bears  $120^{\circ}$  true. This range consists of a triangle on the end of the pier and another triangle a short distance inland. When this range bears  $120^{\circ}$  true change course and steer on it to the pier bearing in mind that the can buoy on the starboard side and the beacon marking the  $2\frac{1}{2}$  patch on the port side, are missing. The port is open to the NE monsoon and is untenable in bad weather.
3. Pier. The Arjo Mining Company maintain the wooden T-shaped pier for loading chrome ore from their mine. The pier is in poor condition. It is not advisable to put ship alongside dock or put out mooring lines on dock. Ship must be placed portside to stern anchor used. Pilotage to and from the pier is compulsory, the fee being P175.00 for each entrance and clearance.
4. Cargo Operations. Ore is conveyed over the pier in tubs by truck - two tubs to a truck of about  $2\frac{1}{2}$  tons each. Labor is supplied locally. Average loading is about 45 tons per gang hour.
5. Provisions. No fresh water is available, but fresh stores in limited quantities can be obtained.
6. Medical Facilities. A small hospital is situated at Santa Cruz.
7. Communications. The local post and telegraph office is located at Santa Cruz.

ONI DECLASSIFICATION/RELEASE INSTRUCTIONS ON FILE

736.54 S U.S. Official's Only  
736.443 S  
Approved For Release 2003/10/01 : CIA-RDP80-00809A000500350162-1  
736.545 S CONFIDENTIAL